

## Review of Modifications and Repairs:

<b>A/C Type:</b> DV 20	<b>Serial No:</b> 20160	<b>Registration:</b> OE-CBW	<b>Year of construction:</b> 1996	<b>Date:</b> 28.09.2021
---------------------------	----------------------------	--------------------------------	--------------------------------------	----------------------------

Modification No.	Description of Modification	Modification / SC - Standard Change / SR - Standard Repair / Repair / Reference	Modification Document Reference:  AFMS:	ICA - Instructions for continuing airworthiness / Compliance times
Issuance No.				
Installation Date on A/C				
SC-V20240/20-1  03.09.2020	"Artex 345 ELT" installed	Artex EASA Standard Change SC-V20240/20-1 CS-SC101b CS-SC004a	Artex ELT 345 Manual Doc. Nr.: Y1-03-0282  AFMS: N/A	24 Months (LTH 40A)  72 Months - Battery Replacement
CS-SC001a  31.08.2017	"TQ Systems KRT-2 VHF COMM" installed	Urbeaero EASA Standard Change CS-SC001a	TQ Systems KRT-2 Installation and Operation Manual Doc. Nr.: DE-3000-800100d  AFMS: N/A	24 Months (LTH 40A)
SC-OE-CBW-16-5101  02.06.2016	"Trig TT21 XPDR" installed	Avionik Plus GmbH EASA Standard Change SC-OE-CBW-16-5101 / CS-SC002a	TT21 / TT22 Installation Manual Doc. Nr.: 00560-00-AO  TT21 / TT22 Operating Manual Doc. Nr.: 00559-00-AF  AFMS: N/A	24 Months (LTH 40A)
EASA MC 10044922  17.05.2013	"Whelen Parmetheus PAR-36 Super-LED Lights" installed	Trieb GmbH EASA Minor Change 10044922	Engineering Order Doc. Nr.: EOMD-012  AFMS: N/A	On Condition